

Dear Customers:



Thank you for using AVA products. We will provide quality products, after-sales service and adequate protection of consumer rights, which is our bounden duty. Therefore in accordance with relevant state regulations, our company implement the following standard warranty service.

I. Warranty service: user can enjoy replacement service of the products bought from our company within 7 days from the date of purchase in the Distributor. (Note: The product performance is damaged but the outlook of the product and accessories is intact, and all products are provided with after-sales service), if there is no local service center, users can send the products to the authorized distributor for warranty service.

II. We don't provide any warranty service for the following causes:

1. The original serial number label has the product is altered, replaced and damaged, or the product does not have serial number, or the product model and serial number on product warranty certificate do not match those of original product.
2. Product exceed the warranty period specified by AVA.
3. Appearance of product is damaged because of abnormal usage.
4. Product's outer packing and attached fittings, the service, attached configuration and giveaways that salesman has committed other than product.
5. Importer storage: If the product is exposed to the humidity and temperature different from normal working environment, its performance may be damaged.
6. Manipulation that is not in compliance with the Manual, abuse, misuse and unauthorized modification can cause damage to the product.

III. Keep this card and valid proof of purchase properly as a warranty service necessary certificates. Please do not modify warranty card and shopping voucher, otherwise it will be considered as void.

IV. The company reserves the final interpretation of product after-service regulations.

## Machine Information

- o Material: Aircraft Aluminum
- o Motor: Carbon Brush Motor (3.5W)
- o Frequency: 0-9000RPM
- o Needle Protrusion: 0-4.5mm
- o Stroke: 3.5mm

## Warranty Card

Product after-sale service commitment table of comparisons

Product type	Commitment policy	Service mode
Motor	Three months warranty	Customer delivery for repair
Machine frame	Three months warranty	
Spare parts	Three months warranty	
Components spare parts beyond the scope of warranty		



**DUKE**  
—Continuing Service

## INSTRUCTIONS

### ① TYPE-C USB

Charging voltage : 5V/2A  
Charging Time: 3 Hours

### ② LED Display Screen

Output voltage: 4.5V-12V

### ③ Add Button

Press + button increase the voltage by 0.1V  
Hold + button increase the voltage by 1V

### ④ Dec Button

Press - button decrease the voltage by 0.1V  
Hold - button decrease the voltage by 1V

### ⑤ ON/OFF & Pause Button

Hold "ON/OFF" button for 1 second to turn ON.  
Press "ON/OFF" button changing over Pause to Working.  
Hold "ON/OFF" button for 2 seconds in pause mode to turn OFF.

### ⑥ RECHARGE

1. Turned on, the number  $\% \%$  is the battery remaining power.
2. Please charge when the battery is below 15%.

## ⚠ WARNING ⚠

- DO NOT DISASSEMBLE PUNCTURE CRUSH, HEAT OR BURN
- Protect the battery from heat (such as from continuous sun exposure), fire and immersion into water. Do not store or operate the battery near hot or flammable objects. There is a risk of explosion.
- When not in use, keep the battery away from paper clips, coins, keys, nails, screws or any other small metal objects that cause the contacts to be bridged.
- A short circuit between the battery contacts may cause burns or result in a fire.
- Do not place the charging unit and the battery near flammable materials. Only charge the battery in dry state and at a fireproof location. There is a risk of fire due to the heat that builds up while charging
- The battery must not be charged unsupervised.